




















220V-240V 50HZ			
CE			
IP54			
			

需要用到的工具		
	X1	
	X1	

提供的附件  螺丝刀*1  塑料螺丝*3  自攻螺丝*3
--



步骤1 	步骤2 	步骤3 	步骤4 	步骤5 	步骤6 	步骤7 
步骤8 	步骤9 	步骤10 	步骤11 	步骤12 	步骤13 